

Technical Data

MEGAFILLER SMOOTH



Product description

Megafiller Smooth is two pack solvent-free epoxy filler that leaves a very smooth surface. The product gives a hard film, but retains excellent sanding properties. It has a lower viscosity than Megafiller and Megafair.

Recommended use

Megafiller Smooth is suitable for above and below-water application. Normally used for re-finishing surfaces treated with Megafiller, or to repair existing epoxy or polyurethane systems. Suitable as part of an epoxy coating system on metal, GRP or wood substrates.

Film thickness and spreading rate

	Minimum	Maximum	Typical
Film thickness, dry (μm)	500	3000	1000
Film thickness, wet (μm)	500	3000	1000
Theoretical spreading rate (m^2/l)	2	0,33	1

Comments

Application range up to 3 mm.

Physical properties

Colour	Off-white
Solids (vol %)*	100 \pm 2
Flash point	>56°C \pm 2

*Measured according to ISO 3233:1998 (E)

Surface preparation

The coating may be used on other substrates. Please contact your local Jotun office for more information.

Condition during application

Apply at a temperature between 10°C and 35°C. The temperature of the substrate should be minimum 3°C above the dew point of the air. The temperature and the relative humidity should be measured in the vicinity of the substrate.

Application data

Mixing ratio (volume)	Trowel, pallet knife or other suitable dispenser. 1 part base + 1 part hardener. Mix the two components thoroughly, in their correct proportions with a knife until the colour is perfectly even (about 2-3 minutes)
Pot life (23°C)	30 minutes
Thinner/Cleaner	Jotun Thinner No. 17 to clean equipment.
Note	May be sanded after 16-24 h (dependent on temperatures)

Drying time

Drying times are generally related to air circulation, temperature, film thickness and number of coats, and will be affected correspondingly. The figures given in the table are typical with:

- * Good ventilation (Outdoor exposure or free circulation of air)
- * Typical film thickness
- * One coat on top of inert substrate

Substrate temperature	10° C	23° C	35° C
Surface dry	14 h	8 h	2 h
Cured	10 d	7 d	3 d
Dry to recoat, minimum	14 h	8 h	2 h
Dry to recoat, maximum ¹	72 h	72 h	48 h

- 1 Provided the surface is free from chalking and other contamination prior to application, there is normally no overcoating time limit. Best intercoat adhesion occurs, however, when the subsequent coat is applied before preceding coat has cured. If the coating has been exposed to direct sunlight for some time, special attention must be paid to surface cleaning and mattening/removal of the surface layer in order to obtain good adhesion.

The given data must be considered as guidelines only. The actual drying time/times before recoating may be shorter or longer, depending on film thickness, ventilation, humidity, underlying paint system, requirement for early handling and mechanical strength etc. A complete system can be described on a system sheet, where all parameters and special conditions could be included.

Instructions for use:

Apply onto suitable undercoats such as **Megacote** or **Megaprimer** or **Megafiller**. Sand **Megafiller Smooth** before covering it to help anchorage. Overcoat with **Megaprimer** and **Megaspeed Undercoat**.

Storage

The product must be stored in accordance with national regulations. Storage conditions are to keep the containers in a dry, cool, well ventilated space and away from source of heat and ignition. Containers must be kept tightly closed.

Handling

Handle with care.

Packing size

2 L Comp. A and 2 L Comp. B

Packing may vary from country to country according to local requirements.

Health and safety

Please observe the precautionary notices displayed on the container. Use under well ventilated conditions. Do not breathe or inhale mist. Avoid skin contact. Spillage on the skin should immediately be removed with suitable cleanser, soap and water. Eyes should be well flushed with water and medical attention sought immediately.

For detailed information on the health and safety hazards and precautions for use of this product, we refer to the Material Safety Data Sheet.

DISCLAIMER

The information in this data sheet is given to the best of our knowledge based on laboratory testing and practical experience. However, as the product is often used under conditions beyond our control, we cannot guarantee anything but the quality of the product itself. We reserve the right to change the given data without notice.

Head Office & Nordic

Jotun A/S
P.O. Box 2021
N-3248 Sandefjord
Norway
Phone +47 33 45 70 00
Fax +47 33 46 46 13

Europe

Jotun Paints (Europe) Ltd.
Stather Road, Flixborough
North Lincolnshire DN15 8RR
United Kingdom
Phone +44 172 44 00 000
Fax +44 172 44 00 100

Middle East

Jotun U.A.E Ltd. LLC.
Al Quoz Industrial Area
P.O Box 3671
Dubai U.A.E
Phone +971 4 3 39 50 00
Fax +971 4 3 38 06 66

South East Asia

Jotun (Singapore) Pte. Ltd.
No 11-15, Sixth Lok Yang
Road
Jurong
Singapore 628 111
Phone +65 6265 4711
Fax +65 6265 7484

Jotun is a World Wide company with factories, sales offices and stocks in more than 50 countries. For your nearest local Jotun address please contact the nearest regional office or visit our website at www.jotun.com

ISSUED 19 OCTOBER 2004 BY JOTUN
THIS DATA SHEET SUPERSEDES THOSE PREVIOUSLY ISSUED

PDF Version :